FILE COPY

SIZGGR40 IST Copy

81266 R40 Geolydrology North Beardary

FLUORIDE

AT THE

NORTH BOUNDARY

OF

ROCKY MOUNTAIN ARSENAL

A Report
by
G. J. Ward
Geologist
Rocky Mountain Arsenal
January 1980

19980911 086

Approved for public resource
Distribution Unlimited

Rocky Mountain Arsenal Information Center Commerce City, Colorado



Aqu98-12-2401

REPORT DOCUMENTATION PAGE

Form Approved OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Artington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.

Davis Highway, Suite 1204, Arington, VA 222	OZ-430Z, and to the Office of Management and	Dudget, 1 aper 11 ork fredeetion 1 1 ojes	((o / o + o / o o /), Tradimigrani, Do Zoodo.
1. AGENCY USE ONLY (Leave blan	nk) 2. REPORT DATE Jan 80	3. REPORT TYPE AND D	ATES COVERED
4. TITLE AND SUBTITLE Fluoride at the North Boundary	of Rocky Mountain Arsenal	5	. FUNDING NUMBERS
6. AUTHOR(S) G. J. Ward			
7. PERFORMING ORGANIZATION I Rocky Mountain Arsenal Commerce City, CO 80022	NAME(S) AND ADDRESS(ES)		. PERFORMING ORGANIZATION REPORT NUMBER 31266R40
9. SPONSORING / MONITORING A	GENCY NAME(S) AND ADDRESS(E	(S) 1	O.SPONSORING / MONITORING AGENCY REPORT NUMBER
11. SUPPLEMENTARY NOTES			
12a. DISTRIBUTION / AVAILABILIT APPROVED FOR PUBLIC RI	Y STATEMENT ELEASE; DISTRIBUTION IS U		2b. DISTRIBUTION CODE
13. ABSTRACT (Maximum 200 w) The purpose of this report is to Arsenal. Both alluvial and Der		fluoride mass flux at the dered.	north boundary of Rocky Mountain
14. SUBJECT TERMS Hydrogeology, Contamination			15. NUMBER OF PAGES 14 16. PRICE CODE
17. SECURITY CLASSIFICATION OF REPORT UNCLASSIFIED	18. SECURITY CLASSIFICATION OF THIS PAGE UNCLASSIFIED	19. SECURITY CLASSIFICA OF ABSTRACT UNCLASSIFIED	ATION 20. LIMITATION OF ABSTRACT

FLUORIDE AT THE NORTH BOUNDARY OF ROCKY MOUNTAIN ARSENAL

1. Purpose and Scope

The purpose of this report is to calculate groundwater flow and fluoride mass flux at the north boundary of Rocky Mountain Arsenal. The calculations were done for the existing bentonite barrier and the extensions of it to the east and to the west. Figure 1 shows the area studied. Both alluvial and Denver formation aquifers are considered.

2. Discussion

a. Alluvial Aquifer

- (1) The mean fluoride values listed in Table 1 are based upon two or more observations except as indicated. The number of wells used in each zone varies because of the distribution of wells in the area.
- (2) The saturated thickness of the alluvial aquifer is based upon the review of stratigraphic cross-sections in the north boundary area. Permeability was estimated from pump tests conducted by the Waterways Experiment Station in 1978 and from calculations done in a report by S. P. Miller of Waterways Experiment Station. The hydraulic gradient was determined from a Rocky Mountain Arsenal water table elevation map.
- (3) Table 2 shows that seventy-one percent of the alluvial water flowing across the north boundary is in zones 4 and 5. The fluoride level in zone 4 is only 0.02 mg/l above the State of Colorado's maximum limit for fluoride in drinking water. That in zone 5 is less than half of the maximum drinking water limit. These two zones represent thirty-six percent of the barrier length but over seventy percent of the water flow.

¹Miller, S.P., Interim Containment System Groundwater Treatment, Rocky Mountain Arsenal, Denver, CO, USAE, Waterways Experiment Station, Soils and Pavements Laboratory, September, 1976.

Well ID	Bore ID	Barrier Zone	ΧF-	Depth
41 1 0P306 125 42 124 20 110 111 123 118 119 120 48	390 25 - 260 391 259 199 691 692 687 682 683 684 397	1 1 1 1 1 **2 2 2 2 2 2 2 2 2	4.56 5.13 4.53 *4.80 *1.17 *3.80 *1.07 3.59 3.79 4.30 5.60 2.72 2.66 3.29	15.4 8.1 - 18.0 16.8 16.0 - 16.0 19.0 20.0 13.5 14.0 13.5

SECTION 24

Well ID	Bore ID .	Barrier Zone	ΧF-	Depth
56 12 6 25 13 5 60 61 59 29 4 30 31	688 183 60 221 209 45 190 191 344 345 119 347 349	2 2 3 3 3 4 4 4 4 4 5 5 5 6	3.99 3.18 3.23 3.48 2.58 2.68 *2.40 2.42 2.41 2.20 1.42 1.08 0.89 0.27	21.0 - 12.8 12.0 13.7 6.1 18.4 17.0 18.0 20.3 9.0 19.4 20.4 44.7

*One Sample **Existing Barrier Zone

TABLE 1

List of wells used to determine F concentration in the bentonite barrier zones of Sections 23 and 24 of Rocky Mountain Arsenal. Fluoride values are in mg/1. Depths are in feet.




FIGURE 1

Area of Study in Sections 23 and 24 of Rocky Mountain Arsenal For clarity, only wells included in the study are shown.

By reducing the flow of water in zones 4 and 5 by 20, 40, 60 and 80 percent, fluoride mass flux changes according to Table 3.

Barrier Zone	1	**2	. 3	A	5	6	Totals
L ft M ft A ft ² K ft/da i Q ft ³ /da Q gal/da Q gal/min XF- mg/l XF- g/gal F g/da	700 7 4900 200 0.0067 6566 49114 34.1 3.18 0.012 589	1500 7 10500 200 0.0067 14070 105244 73.1 3.42 0.013 1368	1500 10 15000 200 0.0067 20100 150348 104.4 3.10 0.012 1804	1000 10 10000 575 0.0067 38525 288167 200.1 2.42 0.009 2594	1300 15 19500 575 0.0067 75124 561928 390.2 1.13 0.004 2248	400 10 4000 200 0.0067 5360 40092 27.8 *0.27 0.001 40.9	6400 63900 1.597 × 10 ⁵ 1.195 × 10 ⁶ 830 ***1.90

length of aquifer

= thickness of aquifer

L·M - cross sectional area

permeability

hydraulic gradient

K-A-I - flow

mean value of F concentration

Q·XF- - mass flux

One Sample

** Existing Barrier Zone
** QTotal/FTotal - XFT Total

TABLE 2

Calculations for water flow and mass flux of F- for each bentonite barrier zone of the alluvial aquifer

Percent Reduction	Q gal/da (gal/min)	F g/da (g/min)	XF ⁻ mg/gal (mg/l)
20	1.025 x 10 ⁶ (712)	7675 g/da (5.32)	7.5 (1.98)
40	8.550 x 10 ⁵ (594)	6707 g/da (4.66)	7.8 (2.06)
60	6.849 x 10 ⁵ (476)	5738 g/da (3.98)	8.4 (2.22)
80	5.151 x 10 ⁵ (358)	4770 g/da (3.31)	9.3 (2.46)

TABLE 3

Changes in mass flux and concentration of \mathbf{F}^{T} at the north boundary of Rocky Mountain Arsenal by reducing water flow through the high permeability zones of the bentonite barrier extension.

The effect upon fluoride level decreasing flow in the zones of high permeability is shown by Figure 2.




FIGURE 2

Reduction of maximum flow required to produce a fluoride concentration in excess of the maximum state limit.

b. Denver Formation

(1) The mean fluoride concentrations in the Denver sands are well below the maximum state limit. Of twenty-six sites sampling water in the Denver Formation, only two exceed 2.40 mg/l. The fluoride values shown in Table 4 are used to create the mean fluoride values used in Table 5.

Site ID	Well ID	Depth Ft	χ̃F"	Barrier Zone
8855 8850 9915 9916 9785 9780 9780 9765 9765 9775 9770 9795 9790 9815 9810 9835 9830 9845 9840 985 9860	23-163 23-164 23-166 23-169 23-161 23-162 24-133 24-132 24-133 24-134 24-135 24-136 24-137 24-138 24-138 24-139 24-140 24-141 24-142 24-143 24-144 24-144 24-145 24-147	46.5 85.0 49.5 71.5 94.0 69.0 107.5 41.0 25.2 50.5 48.0 73.5 90.5 49.0 79.5 49.0 79.0 57.5 82.5	0.37 1.98 *0.34 **5.10 1.18 0.83 0.54 2.30 **2.46 0.69 1.05 1.01 1.24 1.81 0.62 1.21 1.66 1.16 2.24 1.74 1.58 2.23 1.08 1.21 1.30 1.28	111122373333333333444455555

^{*}One sample **Exceeds State Limit

TARLE !

Sites at the north boundary of Rocky Mountain Arsenal sampling groundwater from the Denver formation in Sections 23 and 24. Mean fluoride concentrations, $\overline{X}F^{-}$, are in mg/l(ppm).

- (2) The calculations in Table 5 are based upon the cross-sectional area of Denver sand fifty feet or less below ground surface. This was done because the preliminary design idea for the extension of the treatment system was to construct it to an average depth of fifty feet.
- (3) The permeability of sand units in the Denver formation is two orders of magnitude less than that of the alluvial aquifer. This is based upon a core analysis from Boring 978 of a sand unit at a depth of 110 feet with a laboratory permeability of 2640 millidarcys (7.2 ft/da).
- (4) Boring 975, located at the east end of "Bog", indicates that the regional dip of the Denver formation is to the north. The normal regional dip of the formation is to the south in the vicinity of Rocky Mountain Arsenal. Since the sand units in the formation are completely confined by shale and clay, the hydraulic gradient and the regional dip are the same. The hydraulic gradient shown in Table 5 is roughly twice that of the alluvial aquifer.
- (5) It can be seen from Table 6 that mass flux of fluoride in Denver sands represents only about one percent of the total mass flux of fluoride at the north boundary of Rocky Mountain Arsenal. The total area of bedrock sand mapped along the bentonite barrier alignment is 1,333, 123 square feet. The vertical distribution of Denver sand is shown in Table 7.
- (6) Table 8 shows that total groundwater flow in the north boundary area must be reduced by just over half the maximum amount before the fluoride concentration exceeds the maximum state limit.

Barrier Zone	1	2	3	4	5	Totals
A ft ² K ft/da i Q ft ³ /da Q gal/da Q gal/min XF- mg/l XF- g/gal F g/da	10700 7.2 0.0114 878 6567 4.56 0.36 0.0013	4660 7.2 0.0114 382 2857 1.99 1.24 0.0047	4760 7.2 0.0114 391 2925 2.03 1.12 0.0042 12.3	5660 7.2 0.0114 465 3478 2.41 1.91 0.0072 25.0	11960 7.2 0.0114 982 7345 5.10 1.15 0.0043 31.6	37740 3099 23173 16.1 1.04 0.0039 90.8

TABLE 5

Calculations for water flow and mass flux of ${\sf F}^-$ for each bentonite barrier zone in Denver sand. There are no wells in Zone 6 that sample Denver sand.

Barrier Zone -	1 .	2	3	a,	5	6	Total F
F g/da alluvial	589	1368	1804	2594	2248	40.9	8644
F g/da bedrock	8.54	13.4	12.3	25.0	31.6	-	90.8
F g/da total	597-5	1381.4	1816.3	2619	2279.6	40.9	8734.8
% Falluvial	98.6	. 99.0	99.3	99.0	98.6	-	
% F bedrock	1.4	1.0	0.7	1.0	1.4	-	

TABLE 6

Comparison of fluoride mass flux in the alluvial and bedrock aquifers in different bentonite barrier zones.

Depth Feet	Area	Percent Area
<50	40520	30%
>50	92603	 _ 70%

TABLE 7

Vertical distribution of sands in the Denver formation at the north boundary of Rocky Mountain Arsenal, Sections 23 and 24.

Percent Q	Q, gal/min	Q, gal/dæ	F, g/da	C, mg/gal	C, mg/1
100	846	1.218 × 106	8735	7.2	1.90
80	677	9.753 × 105	7352	7.5	1.99
60	509	7.324 × 105	5968	8.2	2.16
40	340	4.894 × 105	4583	9.4	*2.48
20	171	2.466 × 105	3197	13.0	3.43

^{*}Exceeds maximum state limit

TABLE 8

Groundwater flow and mass flux of fluoride at the north boundary of Rocky Mountain Arsenal combining alluvial and bedrock groundwater. C is concentration of F

c. Fluoride Data

(1) The reliability of mass flux calculations is based largely upon the quality of analytical data for fluoride concentration in groundwater. Historically, fluoride data produced by the MALD at Rocky Mountain Arsenal shows higher values than those produced by the Colorado Department of Health. This difference in analytical values is illustrated in a Memorandum for Record from USATHAMA:

"As fluoride data was evaluated at each well location, it was apparent that duplicate analyses were conducted for the period 1 Jul 75 to 15 Jan 76. The first was performed by the State of Colorado at the same time a second was performed by MALD, RMA. Visual comparison indicated that consistently different results had been obtained. Table 3 represents a statistical comparison of the two sets of analyses. In every case the State of Colorado average is below that obtained by RMA. The difference is approximately 0.3 to 0.4 mg/l. Variation between the two results can probably be related to a difference in the analytic measurement technique. Comparison of the variance indicates that in almost every case, the dispersion of results is greater for RMA. Again, this anomally can be attributed to a difference in analytical measurement techniques."2

- (2) Table 3 from the same Memorandum for Record is presented as Table 9 in this report for visual comparison of the fluoride analytical techniques of Rocky Mountain Arsenal and the Colorado Department of Health.
- (3) While working at the Analytical Systems Branch, Bldg 743, Rocky Mountain Arsenal, the writer conducted an informal study to find out if fluoride concentration in water was dependent upon analytical technique. The established technique, a colorimetric one with a distillation step, was compared to three techniques using an ion specific electrode (ISE) detector. The study was done using actual 360° Program wells and fluoride standards in distilled water. The study indicated that fluoride concentration in the same sample varied according to the analytical technique used. The technique comparison study is presented as Table 10.

²Campbell, D. L., DRCPM-DRR, MFR, 1 February 1978, Evaluation of RMA Fluoride Data.

Comparison of Fluoride Analysis Techniques

	٠						y comp.	
		ORMED	NO DUPLICATE ANALYSES PERFORMED	NO DUPLIC		108	22005	mount vir.
- 0.274	+0.402	0.918 0.644	7.713 8.115	ထထ	골종	105	22004	
•			ARY VINICITY	NORTHWEST BOUNDARY VINICITY				
+ 0.110	+0.365	0.020	2.766	13	중중	122	24001	
+ 0.226	+0.378	0.046	3.988 4.366	8 13	품	115	23004	
+ 0.804	+0.363	0.063	4.289	9 14	E ₹	75	. 23009	- 100
- 0.277	+0.296	0.294 0.0167	2.275 2.571	∞ ∞	품	45 .	24005	10
		PERFORMED	ANALYSES	NO DUPLICATE	~	25	23001	
+ 0.023	+0.157	0.013	1.800	9	₽ ₹	119	24004	· worth · FF.
99.0 +	+0.520	0.042	2.878	9	₽§	. 09	24006	e
+ 1.290	+0.610	0.046	2.700	9	H W	. 121	23005	
		ī	Y VICINITY	NORTH BOUNDARY VICINITY	-	•		
Difference In Varian	Difference¹ In Averages (△ ▼)	Variance ($\langle au^2 \rangle$	Average $\frac{3}{(\overline{\lambda})}$	No. of Data Points	Performin Lab2	Old Well No.	New Well No.	<u>-</u>

¹Time interval includes 75148 to 76013 (1 Jul 75 to 15 Jan 76) ²Gi - State of Colorado, RM - Rocky Mountain Arsenal 3 Expressed in mg/1.

 $\frac{4}{X}$ (RMA) - \overline{X} (State of Colorado) $5 \checkmark$ (RMA) - τ (State of Colorado)

		*1		No. of	Average 3		Difference 4	Difference
	New Well No.	Old Well No.	Lab	Points	concentration (\overline{X})	Variance; (∀*)	In Averages $(\Delta \vec{X})$	In Variand (△∇√)
	NORTHWEST BOUNDARY VICINITY (Continued)	DARY VICINITY (C	Continued)					
1	22003	104	H	11	2.673	0.029		
		,	R.	11	2.825	0.012	+ 0.152	- 0.017
	27001	103	В	6	0.717	0.004		
			RM	Oi	0.791	0.002	+ 0.0/4	200.0 -
			ON	NORTH BASIN F VICINITY	: VICINITY			
	23002	7		NO DUPLICA	NO DUPLICATE ANALYSES PERFORMED	WED		
	23006	132	5	10	2.760	0.086		
			RM	1.5	3,100	0.189	+ 0.340	+ 0.103
	23007	133	ᆼ	j.o	2,420	0.029		
1			RM	15	2.852	0.211	+ 0.432	+ 0.182
1	23008	134	픙	10	2.650	990.0		!
			RM	15	3.266	0.140	9T9.0 +	+ 0.074
	26008	118	픙	10	2,770	0.152		
			RM	10	2.945	0.174	4 0.1/5	+ 0.020
	26007	73	B	6	1.811	0.017		
	•		RM	14	2.100	0.025	+ 0.289	+ 0.008

Table 9

Comparison of fluoride techniques of Rocky Mountain Arsenal and the Colorado Department of Health. 3

(4) Both studies show that fluoride values vary according to the technique used. Specifically, the Colorado Department of Health has produced values 0.3 - 0.4 mg/l lower than those produced by the Analytical Systems Branch, Bldg 743, Rocky Mountain Arsenal, for the same sites. Viewing Table 11 with this in mind, one sees that flow must be reduced to less than forty percent of maximum before the 2.4 mg/l maximum limit of fluoride is exceeded.

Sample	Site ID	Colorimetric w/Distillation	ISE (CDTA) w/Distillation	ISE w/CDTA	ISE No CDTA
A01621 A01622 A01623 A01624 A01625 A01627 A01628 A01629 A01630 A01637 A01662 A01663 A01664 A01665 X2. OSTD X1. SSTD X0. SSTD	20-1 6-1 6-2 7CDDC 30BCCD 26CDBA 35-5 26-1 26-5 27-2 22-2 26-19 26-21 26-22 26-31	1.49 1.07 1.73 2.32 1.58 1.99 1.11 3.50 2.12 1.40 0.45 3.56 2.60 2.76 0.91 2.00 1.58	1.60 1.25 1.84 2.46 1.75 2.51 1.40 3.58 2.54 1.58 0.77 3.75 2.95 3.24 1.16 2.02	1.29 0.90 1.56 1.96 1.42 1.79 1.00 2.92 1.82 1.23 0.35 3.02 2.22 2.48 0.78 2.00 1.54 ±1.06 0.54	1.24 0.90 1.56 1.94 1.41 1.80 0.98 2.86 1.70 1.22 0.35 2.96 2.20 2.40 0.77 2.00

*One Sample

TABLE 10

Comparison of fluoride determination techniques (23 February 1978). Fluoride values are in mg/l (ppm). CDTA is a reagent that prevents fluoride ions from becoming complexed with metal ions.

Fluoride Method	% Maximum Flow to Exceed 2.4 mg/l	Q, gpd (gpm)
RMA	44.4	5.045 × 10 ⁵ (375)
СОН	35.6	4.334 x 10 ⁵ (301)

TABLE 11

Comparison of fluoride methods in relation to groundwater flow at the north boundary.

3. Conclusions

- a. Although nearly eighty percent of the alluvial wells used in this report exceed the 2.4 mg/l fluoride limit, their effect is more than offset by the low values found in barrier zones 4 and 5. This off-setting effect is due to higher permeability in those two zones, which results in higher water flow rates.
- b. If fluoride were the only ion to be considered in the extension of the north boundary treatment system, the eastern end of it could be located in the vicinity of Well 24-29 (boring 345). However, chemical data shows that Nemagon (DBCP) is found in wells east of 24-29.
- c. Since the treatment system would have to be extended to First Creek to intercept Nemagon contamination, fluoride is eliminated as a contaminant in the groundwater. The additional water containing Nemagon has fluoride levels less than one-half of the maximum fluoride limit. When this water is mixed with that from other areas of the north boundary containing higher fluoride concentration, dilution occurs. Thus, fluoride concentration of water entering the treatment plant is well below the maximum limit of 2.4 mg/l.

4. Recommendations

- a. The treatment system should be extended eastward as planned to a point just east of Well 24-32 (Boring 351). By extending the system to this point, it is highly probable that both Nemagon and fluoride will be eliminated as groundwater contaminants at the north boundary of Rocky Mountain Arsenal. This is based upon current chemical data.
- b. It is recommended that a fluoride treatment module not be installed in the expanded treatment system. However, the system should include plumbing connections so that a fluoride module could be easily installed if subsequent chemical data showed the need for one.
- c. Recent chemical data indicates that several organic compounds may be in Denver sand at depths greater than the fifty foot design depth of the expanded north boundary treatment system. upon completion of sampling and evaluation of chemical data from the north boundary area, a recommendation about the depth of the proposed treatment system can be made.